


40-279

Tubeless/Tube-Type



NOTES:

- (1) Refer to Parker Service Bulletin SB7082 for replacement hubcap and seals.
- (2) SB7067-1 Service Bulletin Kit upgrades wheel to 40-279A configuration per SB7067.

FIG.	PART NO.	DESCRIPTION	40-279 (1) (2)
1	161-13301	Inner Wheel Half Assembly	1
2	214-39412	Cup-Bearing	1
3	162-12401	Outer Wheel Half Assembly	1
2	214-39412	Cup-Bearing	1
4	160-01100	Air Valve Assembly	1
5	214-09200	Cone-Bearing	2
6	164-23001	Brake Disc	1
7	154-03900	Molded Grease Seal	2
8	155-08300	Snap Ring	2
9	158-01700	Hub Cap	1
11	103-32800	Bolt (MS21250-06080)	9
12	095-10600	Washer (AN960-616)	9
12A	095-03100	Washer (MS20002C6)	9
13	094-15800	Nut (NAS1804-6N)	9
14	101-50272	O-Ring (MS28775-272)	1