

Cleveland

Wheels & Brakes

Parker Hannifin Corporation

Aircraft Wheel & Brake

1160 Center Road, P.O. Box 158

Avon, Ohio 44011 USA

1-800-BRAKING (272-5464)

440-937-1272 • FAX 440-937-5409

SERVICE BULLETIN

P/N 30-9 BRAKE ASSEMBLY - REWORK TO P/N 30-9D CONFIGURATION

EFFECTIVITY: For all Parker Hannifin 30-9 Brake Assemblies as installed on the Diamond Aircraft Industries, Model K-20 or assemblies in inventory at Diamond.

REASON: To reconfigure the 30-9 Brake Assembly with a new torque plate assembly that will mount to the axle flange with 5/16 diameter bolts.

DESCRIPTION: Remove existing torque plate 075-00800 and replace with 075-19300 Torque Plate. Re-identify nameplate on the brake assembly by hand pressing a suffix letter "D" to the "30-9" part number on the nameplate using a character stamp stylus or ball point pen with a height of .125 inches. Revise aircraft records accordingly. Return any unaltered 075-00800 Torque Plates to Parker Hannifin.

COMPLIANCE: Mandatory.

APPROVAL: The design contents of this service bulletin are FAA DER approved. Compliance with this service bulletin does not alter FAA TSO approval.

WEIGHT & BALANCE: No change..

PUBLICATIONS: Part number 30-9D information to be incorporated into the Parker Product Catalog at next revision.