

Cleveland

Wheels & Brakes

Parker Hannifin Corporation

Aircraft Wheel & Brake

1160 Center Road, P.O. Box 158

Avon, Ohio 44011 USA

1-800-BRAKING (272-5464)

216-937-1272 • FAX 216-937-5409

SERVICE BULLETIN

HEAT CRACKS IN PIPER AZTEC BRAKE DISC, PART NUMBER 164-03206

- PURPOSE:** To advise Aztec owners that small heat checks on the wearing surface of the brake disc, P/N 164-03206, can be expected to develop during normal service operations. The 164-03206 brake disc is part of the 3080D wheel assembly.
- INSPECTION
PROCEDURE:** At each periodic maintenance inspection, visually inspect both wearing surfaces of brake disc, P/N 164-03206, for heat checks or cracks.
- ACCEPTANCE:** Heat checks are considered to be superficial surface cracks and are not detrimental to the integrity or performance of the braking system.
- REJECTION:** Replace brake disc if crack length exceeds .800 inch or crack depth exceeds .340 inch.
- If crack depth is not measurable, replace brake disc if crack length exceeds .400 inch.