

# Cleveland

Wheels & Brakes

Parker Hannifin Corporation

**Aircraft Wheel & Brake**

1160 Center Road, P.O. Box 158

Avon, Ohio 44011 USA

1-800-BRAKING (272-5464)

216-937-1272 • FAX 216-937-5409

# SERVICE BULLETIN

## HEAT CHECKS IN PIPER AZTEC BRAKE DISC PART NUMBER 164-05700

- PURPOSE:** To advise Aztec owners that small heat checks on the wearing surface of the brake disc, P/N 164-05700, can be expected to develop during normal service operations. The 164-05700 brake disc is part of the 40-131 wheel assembly.
- INSPECTION  
PROCEDURE:** At each periodic maintenance inspection, visually inspect both wearing surfaces of brake disc, P/N 164-05700 for heat checks or cracks.
- ACCEPTANCE:** Heat checks are considered to be superficial surface cracks and are not detrimental to the integrity or performance of the braking system.
- REJECTION:** Replace brake disc if crack length exceeds .800 inch or crack depth exceeds .280 inch.
- If crack depth is not measurable, replace brake disc if crack length exceeds .400 inch.