

# Cleveland

Wheels & Brakes

Parker Hannifin Corporation

**Aircraft Wheel & Brake**

1160 Center Road, P.O. Box 158

Avon, Ohio 44011 USA

1-800-BRAKING (272-5464)

216-937-1272 • FAX 216-937-5409

# PRODUCT REFERENCE MEMO

## **APPLICATION OF NEW LABEL TO 30-107/40-107 SERIES WHEEL AND BRAKE TO INDICATE REQUALIFICATION FROM TSO C26b TO TSO C26c**

### **MATERIALS**

**REQUIRED:** Four (4) nameplates, part number 166-10400, per aircraft

**APPLICABILITY:** Gulfstream American or Rockwell, Commander Models: 560F, 680F, 680FL(P), 680T, 680V, 680W, 681, 690, 690C (840), 690D (900), 695 (980) AND 695A (1000): those equipped with Cleveland Brake Assembly 30-107 or 30-107A, and Wheel Assembly 40-107 or 40-107A

Within the next 100 hours, perform the following:

1. Locate existing nameplates on each wheel and brake. If dated 7-82, or earlier, proceed to "2". If dated 8-82, or later, no service need be performed per this PRM. (Make log book entry stating such.)
2. Clean surface adjacent to each nameplate.
3. Apply new nameplate, part number 166-10400 to clean surface next to each existing nameplate.
4. Make a log book entry showing compliance to PRM29.